

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

Fig. 1




Fig. 2




Fig.3




Fig.4




Fig.5




Fig.6






Fig.7






# Fig.8



# Fig.9



# Fig.10




Fig.11






Fig.12



# Fig.13



# Fig.14

Fig.14 is a perspective view of a cross-shaped cable connector assembly 600. The assembly features a central cross-shaped body 39X with three ports labeled "OUT" (top, left, and bottom). The top port is connected to a cable 30 via a plug 38 and a sleeve 612. The left port is connected to a cable 40 via a plug 42 and a sleeve 622. The bottom port is connected to a cable 50 via a plug 54 and a sleeve 632. The right port is connected to a cable 60 via a plug 62 and a sleeve 642. Various other components are labeled with numbers: 32, 34, 36, 616, 36, 68, 67, 62, 60, 640, 646, 66, 644, 636, 56, 634, 632, 52, 50, 624, 48, 46, 626, 620, 58, 630, 44, 622, 42, 40, 600.




Fig.15






Fig.16




Fig.17




Fig.18

